

ATTACHMENT E

7 January 2015 Inspection Report

CENTRAL VALLEY REGIONAL WATER QUALITY CONTROL BOARD

Irrigated Lands Regulatory Program Enrollment Confirmation Inspection Report

Ownership Information:

| | | | | | |
|-----------------------|-----------------------|-------------------|----------------------|----------------|--------|
| Owner (s): | Athwal Investments LP | Coalition: | East San Joaquin WQC | County: | Madera |
| Parcel Number: | 023-050-016 | Acres: | 56.5 | | |

Inspection Findings:

| | |
|--|---|
| Date Inspected: | 7 January 2015 |
| Inspected By: | Lisa Wilson & Wesley Ouimette |
| Type of Inspection: | Commercially Irrigated Agriculture |
| Crop type: | Almond |
| Irrigation Method: | Micro Sprinkler |
| Distance to Surface Water: | 0.1 mile south of the Chowchilla River |
| Potential to Discharge to SW: | Inconclusive |
| Discharge Notes: (Photos included on subsequent pages.) | <p>Photo Site 1: North side of property: No discharge points seen. Supply canal between property and road.</p> <p>Photo Site 2: Northeast Corner of Property: No discharge points seen. Supply canal between property and road. No pipes or erosion features at canal. Property sits below canal.</p> <p>Inspection found no direct evidence of potential to discharge to surface waters.</p> |

| | | |
|-----------|---|--|
| Approved: |  | |
|-----------|---|--|

Photo Site 1:



Photo Site 2:



CENTRAL VALLEY REGIONAL WATER QUALITY CONTROL BOARD

Irrigated Lands Regulatory Program Enrollment Confirmation Inspection Report

Ownership Information:

| | | | | | |
|-----------------------|-----------------------|-------------------|----------------------|----------------|--------|
| Owner (s): | Athwal Investments LP | Coalition: | East San Joaquin WQC | County: | Madera |
| Parcel Number: | 024-142-017 | Acres: | 36.9 | | |

Inspection Findings:

| | |
|--|--|
| Date Inspected: | 7 January 2015 |
| Inspected By: | Lisa Wilson & Wesley Ouimette |
| Type of Inspection: | Commercially Irrigated Agriculture |
| Crop type: | Almond |
| Irrigation Method: | Drip |
| Distance to Surface Water: | 1 mile east of Berenda Slough |
| Potential to Discharge to SW: | Inconclusive |
| Discharge Notes: (Photos included on subsequent pages.) | <p>Photo Site 1: Northeast corner of property: No discharge points seen. Supply canal between property and road. No pipes or erosion features at canal. Property sits below canal. Trees are small, most likely not producing.</p> <p>Photo Site 2: Southwest corner of property. Concrete pipe goes underground to concrete stand pipe. Staff believe may be remnants of old flood system. Stand pipe includes a float valve.</p> <p>Inspection found no direct evidence of potential to discharge to surface waters.</p> |

| | | |
|-----------|---|--|
| Approved: |  | |
|-----------|---|--|

Photo Site 1, Photo 1:



Photo Site 1, Photo 2:



Photo Site 2: Photo 1



Photo Site 2: Photo 2



CENTRAL VALLEY REGIONAL WATER QUALITY CONTROL BOARD

Irrigated Lands Regulatory Program Enrollment Confirmation Inspection Report

Ownership Information:

| | | | | | |
|-----------------------|-----------------------|-------------------|----------------------|----------------|--------|
| Owner (s): | Athwal Investments LP | Coalition: | East San Joaquin WQC | County: | Madera |
| Parcel Number: | 023-050-013 | Acres: | 56.6 | | |

Inspection Findings:

| | |
|--|--|
| Date Inspected: | 7 January 2015 |
| Inspected By: | Lisa Wilson & Wesley Ouimette |
| Type of Inspection: | Commercially Irrigated Agriculture |
| Crop type: | Almond |
| Irrigation Method: | Micro Sprinkler |
| Distance to Surface Water: | 1.1 miles east of Berenda Slough |
| Potential to Discharge to SW: | Inconclusive |
| Discharge Notes: (Photos included on subsequent pages.) | <p>Photo Site 1 (West side of Property) & Photo Site 2 (Northeast side of Property) have same features: No discharge points seen. No ditch between property and road. No erosion features. Property sits at/slightly lower than road. Major storm event to create a possible surface water discharge. Canal near property has no discharge pipes to property and sits above property/road.</p> <p>Inspection found no direct evidence of potential to discharge to surface waters.</p> |

| | | |
|-----------|---|--|
| Approved: |  | |
|-----------|---|--|

Photo Site 1: Photo 1



Photo Site 2: Photo 1

