

California Water Service Company Polhemus Creek Spills - Inspection Photos -

Photos were taken by Regional Water Board Staff during staff's site inspection of September 28, 2007. The inspection's purpose was to assess the aquatic impacts resulting from the California Water Service Company's September 25 & 27, 2007, chloraminated potable water discharges to Polhemus Creek.



**Dead Fish in Polhemus Crk
9-28-07 Photo #1 (HTK)**



Dead Steelhead Recovered from Polhemus Crk by M. Fawcett SFPUC's Contract Biologist on 9-28-07 Photo #2 (HTK)



Dewatering Pumps and Cofferdam at Polhemus Crk Restoration Site – Upstream (South End) of Isolated Work Area 9-28-07 Photo #3 (HTK)



**Under Construction Polhemus Crk Restoration Site
– Erosion Due to Unexpected Discharges
9-28-07 Photo #4 (HTK)**



**Polhemus Crk Restoration Site – Remain of Discharges
9-28-07 Photo #5 (HTK)**



**Polhemus Crk Restoration Site – Under Construction
9-28-07 Photo #6 (HTK)**



Utility Lines Across (Downstream) North End of Polhemus Crk
Restoration Site 9-28-07 Photo #7 (HTK)



**Siltation at North End of Polhemus Crk
9-28-07 Photo #8 (HTK)**



Hay Bails in Polhemus Crk – Downstream Coffer Dam of Restoration Area 9-28-07 Photo #9 (HTK)



North End of Polhemus Crk Restoration Site
Close Up 9-28-07 Photo #10 (HTK)



Polhemus Crk Pool Below Culvert-Fish Barrier –
Downstream of Restoration Area

9-28-07 Photo #11 (HTK)



**North End Pool Below Culvert – Fish Barrier
9-28-07 Photo #12 (HTK)**



**Polhemus Crk Near Confluence San Mateo Crk
9-28-07 Photo #13 (HTK)**



**San Mateo Crk ~ 1.5 Miles Downstream of Polhemus Crk Restoration Site
9-28-07 Photo #14 (HTK)**



**San Mateo Crk ~ 1-2 Miles Downstream of Polhemus Crk
Photo #15 (HTK)**