

**DelFrate, Todd@Waterboards**

---

**From:** Phil Graham <PGraham@recology.com>  
**Sent:** Friday, December 12, 2014 9:30 AM  
**To:** DelFrate, Todd@Waterboards  
**Cc:** Paul Yamamoto; Dave Vaughn; Drew Lehman  
**Subject:** FW: Over flow notification

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Todd,

In addition to the site conditions observed by RWQCB staff during their site inspection commencing at around 10:00 am on December 11, and as required by Monitoring and Reporting Program R5-2014-0830 for Recology Yuba Sutter and Feather River Organics, I am notifying you that at approximately 3:00 am on December 12, storm water being pumped into the storage tanks in the North tank area overflowed but was kept within the compost containment area and pumped back into the storage tanks. At approximately 3:25 am on December 12, storm water overflowed from Vault 2 into the temporary lined emergency overflow basin in the Hog Farm area. The water that overflowed was captured in the lined basin and pumped into the storage tanks for disposal or use as compost make-up water. Site weather station data indicate that during the 24-hour period from December 11 at 4:00 am to December 12 at 4:00 am, the site received 3.56 inches of rainfall, which exceeds the 25-year/24-hour standard of 3.16 inches.

Please call if you have questions.

Phil Graham  
Organics & Landfill Manager  
Recology Ostrom Road  
235 N. 1st Street | Dixon, CA 95620  
T: 530.743.6321 | F: 530.743.8649 [pgraham@recology.com](mailto:pgraham@recology.com)  
(a Recology™ company)

---

NOTICE: This communication may contain privileged or other confidential information. If you have received it in error, please advise the sender by reply email and immediately delete the message and any attachments without copying or disclosing the contents. Thank you.