Agency	Facility	Type	Program	Date	Description	Comments	Corrective Action	Action	County
					Blockage in main caused a 50,000-gallon		Line blockage cleared, spill area		
Arroyo Grande, City					manhole overflow from 410 E. Branch St.	Further enforcement pending	cleaned, creek posted with	NOV sent	
of	Collection WDR	sso	NON15	3/15/07	to Arroyo Grande Creek.	investigation.	warning signs.	3/30/07	San Luis Obispo
O Dida.	C				F-00.	Poor compliance history. Further			
Cypress Ridge	Cypress Ridge	051/	NONAE	247/27	Effluent turbidity limit is 2 NTU, reported	enforcement action currectly being	None reported, violations not		
Limited Partnership	Sewer Facility	OEV	NON15	3/1//0/	value is 2.4 NTU	evaluated.	identified by Discharger.	<u> </u>	San Luis Obispo
Cypress Ridge	Cypress Ridge		1		Efficient to which have to a NITH compared	Poor compliance history. Further			
Limited Partnership		OEV	NON15	2/10/07	Effluent turbidity limit is 2 NTU, reported value is 2.4 NTU	enforcement action currectly being	None reported, violations not		L
Linked Faithership	Sewel Facility	OEV	INCINIO	3/10/07	value is 2.4 NTO	evaluated.	identified by Discharger.		San Luis Obispo
Cypress Ridge	Cypress Ridge				Effluent turbidity limit is 2 NTU and the	Poor compliance history. Further enforcement action currently being	Nama ramantan si-lati		
Limited Partnership	, ,,	OEV	NON15	3/26/07	reported value is 2.5 NTU	evaluated.	None reported, violations not		Carrie Object
Emilieu i alaicionip	Dewel Facility	OLV	INOIVIO	3/20/01	reported value is 2.5 N TO	Poor compliance history. Further	identified by Discharger.		San Luis Obispo
Cypress Ridge	Cypress Ridge	İ			Effluent turbidity limit is 2 NTU and	enforcement action currently being	Nama yawadadialatiaaa ast		
	Sewer Facility	OEV	NON15	3/27/07	reported value is 3.3 NTU	levaluated.	None reported, violations not		Cam Lasta Obiana
Limited Futitioning	OCTO T GOINTY	CLV	1101113	SIZITOI	reported value is 5.5 1410	evaluateu.	identified by Discharger.		San Luis Obispo
	<u> </u>								
]		ŀ			The Discharger adequately			
			j			contained and cleaned up the spill.			
						The spill was captured with a			
	1					vacuum truck. The Discharger			
		l]		prohibited the contractor from using			
		i			•	plugs from blocking the flow line.			
				İ		The Discharger directed the			
			1		Contractor installed sewer plug which	contractor to use pumps to pump			j
			į		caused 400-gallon sewage spill from 905	water to the nearest downstream			
	Goleta SD		İ		S. Patterson Ave.,Goleta, to concrete	manhole. No water bodies were			
Goleta SD	WWTP	sso	NPDES	3/5/07	gutter and street.	affected.	No further action at this time.		Santa Barbara
									Cuita Baibaia
						Discharger implementing salts			
						reduction plan including RO. No			
	Laguna County	ŀ			Chloride 12-month mean. Limit is 150	further enforcement action needed at	Discharger implementing salts		
Laguna Sanitation	SD	CAT 1	NON15	3/31/07	mg/L, reported value 207 mg/L	this time.	reduction plan including RO.		Santa Barbara
							Continuing to pursue source		
	1						control activities to reduce		
	1			į	Chloride violation: limit is 107mg/L and	No further enforcement action	discharges from self-		
Nipomo CSD	Black Lake	CAT 1	NON15	3/8/07	reported value is 119 mg/L.	needed at this time.	regenerating water softeners.		San Luis Obispo
								·	zere obiopo
					Roots in City sewer line caused 300				
		1			gallon- sewage spill from manhole				
San Luis Obispo,	San Luis				overflow at 1699 Phillips Lane San Luis	Section of line is on list for	Vacuumed manhole and edge of		
City of	Obispo WWTP	sso	NPDES	3/5/07	Obispo, to San Luis Creek and land.	replacement in July 2008.	street. Disinfected with bleach.		San Luis Obispo
<u> </u>		 	†		- I al an ages, many paragraph settings		STOCK CHARACTER WILL DIGACIT.	 	Cuit Luis Obispo
						Discharger contained spill with and			
					, , , , , , , , , , , , , , , , , , ,	Discharger contained spill with sand			
				1		bags and cleared the blockage with			
		1				a hydro jetter truck. Excess water			
		1				vacuumed prior to contact to storm			[
					Overflow from making a second	drain system. Line was CCTVed			i
Canta Danhana Ott.	 				Overflow from public sewer main caused	and placed on preventative			
Santa Barbara, City		000	NDDCC	204.07	1000 gal, sewage spill from 1880 Barker	maintenance program with more			
of	WWTP	sso	NPDES	3/31/07	Pass Rd. to land.	frequent visual monitoring.	No further action at this time.		Santa Barbara

Agency	Facility	Туре	Program	Date	Description	Comments	Corrective Action	Action	County
Santa Cruz DPW	Santa Cruz WWTP	sso	NPDES	3/15/07	Sewage leaking from pipe caused 25	Caused by break in force main coupling. Probable slight adverse effect because spill was small.	Contained spill with earthen berm until vac truck removed spill. Replace force main.		Santa Cruz
Santa Cruz DPW	Santa Cruz WWTP	sso	NPDES	3/20/07	Main overflow caused 100-gallon sewage	Dry creekbed absorbed spill. City staff washed roadway and vacuumed up spill remainder, flushed creek with fresh water and cleaned sewer main.	None		Santa Cruz
South County Regional WW Authority	SCRWA WWTP	sso	NPDES		Blockage in sewer main caused 13,000 gal. sewage spill from Spring Ave. and Monterey St. in Morgan Hill to Little Llagas Creek and land.	Flushed clothing and other objects are blocking sewer. Discharger recently cleaned line several times.	Discharger shall investigate improving sewer line and adding recommendations to monthly mailer currently distributed.		Santa Clara

2