

Santa Ana Regional Water Quality Control Board

UPDATE TO THE AGENDA ANNOUNCEMENT

REGIONAL BOARD MEETING
Friday, September 16, 2016 at 10:00 A.M.
Irvine Ranch Water District
(Multi-Purpose Room)
15600 Sand Canyon Avenue
Irvine, CA 92618

(Prepared: 9-2-16)

Item 10 of the original Agenda Announcement contains a minor adjustment, and it is struck through:

Item: *10 **Individual Waste Discharge Requirements for the ~~former~~ Triumph Processing Site – Embee Division, Santa Ana** – Board Staff will ask the Regional Board to consider adopting proposed waste discharge requirements that would authorize in-situ injections of chemical amendments such as soy bean oil, sodium bicarbonate, surfactants, Accelerite[®], Rhodamine tracer, calcium polysulfide and KB-1Plus[®] bioaugmentation agent, to remediate chlorinated solvents, perchlorate and hexavalent chromium-impacted groundwater stemming from historical site operations conducted at the facility.

ITEM NO. 9

September 16, 2016

ERRATA SHEET

Order No. R8-2016-0034
Waste Discharge Requirements for
USA Waste of California, Inc.,

El Sobrante Landfill

Corona, Riverside County

(Language added is underlined)

(Language deleted is ~~strike out~~)

1. Order No. R8-2016-0034, Page 11 of 31, make the following correction to Finding 47:

47. The Discharger has indicated that, on average, approximately 330 tons of CRT panel glass will be accepted each month for disposal at ESL. Delivery and disposal will be performed in accordance with the protocol contained in the ~~Waste Acceptance Program (WAP)~~ described in Finding 44 above, as well as a supplemental protocol specifically addressing CRT panel glass that has been added to the WAP.

2. Order No. R8-2016-0034, Page 12 of 31, add the following heading after Finding 51:

Delegation of Authority

3. Order No. R8-2016-0034, Page 12 of 31, add the following as Finding 52:

52. This Order delegates authority to the Executive Officer to require that the Discharger:

- a. Revise the WAP and/or the methods and procedures for monitoring, reporting, managing, accepting, reusing, and/or disposing of incinerator ash, contaminated soils, CRT panel glass, and/or waste-derived materials at ESL to address newly discovered or newly developed information and/or regulatory guidelines.
 - b. Revise the Monitoring and Reporting Program (MRP) No. R8-2016-0034.

4. Order No. R8-2016-0034, Page 21 of 31, make the following correction to Finding 21:

21. **Concentration Limits** – The concentration limit for any given Constituent of Concern (COC) or Monitoring Constituent in a given monitored medium at ESL shall be in accordance with Title 27, §20400. These limits are specified in the attached ~~Monitoring and Reporting Program (MRP)~~.

5. Order No. R8-2016-0034, Page 22 of 31, add the following as Provision 26:

26. The Executive Officer is hereby authorized:

a. To require, based upon newly discovered or newly developed information and/or regulatory guidelines, that the Discharger revise the WAP and/or the methods and procedures for monitoring, reporting, accepting, managing, reusing, and/or disposing of the materials listed below at ESL:

- i. Incinerator Ash;
- ii. Contaminated Soils;
- iii. CRT Panel Glass;
- iv. Waste-Derived Materials.

b. To require and approve changes to MRP No. R8-2016-0034.