



Photo 2: Internal sampling point (#2) delineated by yellow oval; view to the north from the access road along the top of the south bank of San Jose Creek; note grouted rip-rap slope and stenciled black "RP23" on white background in bottom center of photo marking location of Relief Point 23.