



**FIGURE 4**  
**DETECTED ANALYTES IN SOIL**  
 Toyota of Santa Barbara  
 5611 Hollister Avenue  
 Goleta, California  
 Addendum Additional Soil Characterization



- EXPLANATION**
- Soil Sample Location
  - MW-1 ● Monitoring well location
  - Sample grid
  - ✕ Fence
  - - - Property line
  - ▣ Concrete Pad



**TOYOTA OF SANTA BARBARA PROPERTY**

**GRAHAM NISSAN PROPERTY**

Approximate Limit of Soil Contamination Above Investigation Level Guideline Concentrations in 1997 (Dames & Moore, 1997)

Estimated Extent of Impacted Soil in 2004

Approximate Groundwater Flow Direction

Compressor Shed

Excavation Footprint

Former 2,000-Gallon Gasoline Tank Location (12' deep)

GP-9

GP-2

GP-7

GP-4

GP-8

MW-1

GP-3

GP-6

GP-5

GP-1

GP-14

GP-13

GP-12

GP-11

GP-10