


ATTACHMENT 1



**LEGEND**

- ⊕ SHALLOW GROUNDWATER MONITORING WELL
- ⊖ WELL BURIED AND/OR DAMAGED
- ⊕ DEEP GROUNDWATER MONITORING WELL
- SUPPLY WELL
- X—X— CHAIN-LINK FENCE

NOTE: Source of map provided by ENSR



0 120  
Approximate Scale in Feet



**SECOR**

3437 Empressa Drive, Suite A, San Luis Obispo, CA 93401

**PCE CONCENTRATION IN GROUNDWATER  
FEBRUARY 2005**

**SCOTTS VALLEY DRY CLEANERS  
272A MOUNT HERMON ROAD  
SCOTTS VALLEY, CALIFORNIA**

FILE NAME:

PROJECT NUMBER:

DRAWING DATE:

CAD:Scotts Valley/Remediation/scottsvalley\_remediation.dwg

100T.05932.01.0003

13 MAY 03

Item No. 14 Attachment No. 1  
May 12-13, 2005 Meeting  
SLIC Cases