

Storm Water Multiple Application & Report Tracking System

SMARTS Inspection Details

Inspection Date: 12/12/2014 **Inspection ID:** 2025949

Inspection Type: Non-compliance Follow-up

WDID: 9 37C369565

Owner / Operator: WM Builders
9948 Hibert Street Ste 210
San Diego , CA 92131 **Facility/Site:** La Jolla Del Rey Phase 1
6316 Gullstrand Street
San Diego, CA 92122

Inspector: Chiara Clemente - Regional Board

Agency: Regional Board

Met With: None

Violations: Yes

Follow Up Action: Follow-up Inspection Needed

Notes: I conducted a follow-up site visit (from Wayne Chiu's 12/4/2014 inspection) at 11:50 am while it was raining. No one was present on site, so I walked the perimeter and observed sediment laden discharges along the site perimeter.

Violations:

Violation ID	Violation Type	Occurrence Date	Violation Source	Status
857335	Deficient BMP Implementation	12/12/2014	Inspection	Violation
857333	Unauthorized NSWD	12/12/2014	Inspection	Violation


Attachments:

Attachment ID	File Type	File Title	File Description	Part No.
---------------	-----------	------------	------------------	----------

All Pictures taken by Chiara Clemente

La Jolla Del Rey Phase I- WDID 937C369656; SM-828551; 12-12-14





Phase I- WDID 937C369656; SM-828551; 12-16-14





Phase II- WDID WDID 937C368646; SM-827215; 12-12-14













Phase II- WDID WDID 937C368646; SM-827215; 12-16-14



