



Key

<ul style="list-style-type: none"> On-Site Monitoring Well (October 2007) Off-Site Monitoring Well (May 2016) Off-Site Monitoring Well (November 2016) 	<ul style="list-style-type: none"> Property Boundary Temporary Pilot Test Monitoring Well (June 2017) Temporary Pilot Test Monitoring Well (August 2017) 	<ul style="list-style-type: none"> ND Not Detected NS Not Sampled Off-Site Monitoring Well (May 2019) 	<ul style="list-style-type: none"> Sample result exceeds Site Clean Up Level Observed Groundwater Gradients (May 2020) 	<ul style="list-style-type: none"> Exploration ID Detected Constituent Constituent Concentration, ug/L Well Screen Interval 	<ul style="list-style-type: none"> North Arrow Approximate Scale in Feet
--	--	---	--	---	--

geologica
San Francisco, California

**Marinwood Plaza/
Former Prosperity Cleaners**
187 Marinwood Avenue
San Rafael, California

Figure 3
Distribution of VOCs in
Groundwater Monitoring Wells
May 2020