


Suisun Bay. Operations by C&H required water with less than 50 mg/L chloride concentration.¹⁶ Additional detail on C&H operations and the detailed barge travel data are included in Appendix D.



**Figure 3-8 – Map of Suisun Bay and Western Delta
with locations of continuous monitoring stations**

C&H barges traveled up estuary from Crockett (yellow star). Locations of IEP continuous monitoring stations are shown in red. Scale in miles is indicated in the upper left corner of the map.